

PARTS DEPARTMENT BULLETIN

DATE: 25-Feb-15

BULLETIN NUMBER: 2015-2


SUBJECT: Over Speed Board Part Numbers 46723 and 48801 are superseded to 56075.

MODELS

AFFECTED: 5.0 BCG, 4.2 BCG, 5.0 BCGA, 4.2 BCGA, 7.0 BCGC, 5.8 BCGC, 7.0 BCGD, 5.8 BCGD

DETAIL: Improvements have been made to the over speed board used on the above listed models. This new board uses component surface mount technology increasing reliability. Trouble shooting this board is identical to the old style board. It plugs right into the existing wire harness with no other modifications.

The new board eliminates the need for two separate board part numbers for 50 or 60 Hz use. Board PN 56075 directly replaces boards 46723 and 48801. Easy field conversion of board is done by simply flipping a dip switch.



Over Speed Board Kit PN 56075