


ECO NO.	DATE	REV.	REVISION RECORD	AUTH.	DR. BY
2796	8-11-55	A	ADDED VARISTOR TO FLASHER CRT.		HVY
2942	4-4-59	B	REPLACE ALTERNATOR; ORIGINAL IS NOW SECOND CONFIGURATION; DIODE IN4002 WAS IN5914B		MRK



TOLERANCES (UNLESS OTHERWISE NOTED)		WESTERBEKE CORPORATION TAUNTON, MA. 02780	
.XX	±.02	.XX	±.10
.XXX	±.003	.XXX	±.13
CAS	±.03		
FINISH			
DIMENSIONS		DRAWN BY	DATE
<INCHES>		APPROVED BY	DATE
<MILLIMETERS>		SCALE	NONE
(OTHER APPLICABLE)		SHT. 1 OF 1	E

32.0KW BEDAR MEDICAL COACH
40169